



**THIS BULLETIN IS FAA APPROVED FOR ENGINEERING DESIGN**

**SUBJECT:** Mooney M20R and M20TN with United Instruments, Inc. 5934 series altimeters Factory installed, as well as, altimeters ordered through Mooney Service Parts Department during the specified time frame of the United Instruments, Inc. Service Bulletin No. 13 dated March 25, 2016 .

**MODELS/ SN  
AFFECTED:** M20R - 29-0523 thru 29-0525 (Factory installed)  
M20TN - 31-0140 thru 31-0143 (Factory installed)

**TIME OF  
COMPLIANCE:** **Comply with this AD within the compliance times specified, unless already done.**

**INTRODUCTION:** The purpose of this Service Bulletin is to identify the United Instruments, Inc. Service Bulletin No. 13, dated March 25, 2016 and FAA AD 2017-04-06 United Instruments, Inc.: Amendment 39-18801; Docket No. FAA-2016-9345; Directorate Identifier 2016-CE-028-AD.

This AD applies to United Instruments, Inc. 5934 series altimeters that were manufactured between January 2015 and February 2016 and installed in airplanes and helicopters.

(1) The specific affected serial number altimeters can be found in United Instruments, Inc. Service Bulletin No. 13, dated March 25, 2016.

(2) Altimeters that have been corrected by United Instruments, Inc. following Service Bulletin No. 13, dated March 25, 2016, are not affected by this AD and no further action is necessary.

(3) Altimeters that have been corrected by United Instruments, Inc. can be identified by a yellow dot, approximately 1/4 inch (6 mm) in diameter, located approximately 1 inch (25 mm) to the left side of the nameplate. The corrected altimeters will also have a letter "M," approximately 1/8 inch (3mm) high, metal stamped on the nameplate after the name "ALTIMETER."

**The attached compliance card needs to be filled out and returned to Mooney International Corporation upon completion of this Service Bulletin M20-326.**

**INSTRUCTIONS:** **Read entire procedures before beginning work.**

**WARRANTY:** Refer to United Instruments, Inc. Service Bulletin No. 13 Dated March 25, 2016

**REFERENCE  
DATA:** 1. United Instruments, Inc. Service Bulletin No. 13, dated March 25, 2016  
2. FAA AD 2017-04-06 United Instruments, Inc.: Amendment 39-18801; Docket No. FAA-2016-9345; Directorate Identifier 2016-CE-028-AD.

**PARTS LIST:** Refer to United Instruments, Inc. Service Bulletin No. 13 Dated March 25, 2016



**THIS BULLETIN IS FAA APPROVED FOR ENGINEERING DESIGN**

<b>MOONEY INTERNATIONAL CORPORATION</b> KERRVILLE, TEXAS 78028 - FAX 830-257-4635	
SERVICE (BULLETIN) (INSTRUCTION) NO. _____ HAS BEEN COMPLIED	
WITH ON AIRCRAFT MODEL _____ SERIAL NUMBER _____	
Tach. Time: _____	N-Number _____ (Reg. No.)
Owner: _____	Date of Compliance: _____
_____	Complied
_____	By: _____
Inspection Report: _____	
_____	
_____	
Form 07-0001	
<b>MOONEY INTERNATIONAL CORPORATION</b> ATT'N: TECHNICAL SUPPORT 165 Al Mooney Road, North Kerrville, Texas 78028	

PLACE  
STAMP  
HERE

**SEND TO: Mooney International Corporation**  
165 Al Mooney Road North  
Kerrville, TX 78028  
FAX: (830) 257-4635 or EMAIL [support@mooney.com](mailto:support@mooney.com)

**Figure SB M20-326-1 - Compliance Card**